




Volkswagen ID. Buzz as of 2022







1. Identification / recognition




Document number rds_vwn_MEB41b_002_en



Volkswagen **ID. Buzz**

as of 2022





Volkswagen ID. Buzz as of 2022

6. In case of fire





Lithium-ion batteries can become damaged or improper Use promptly or with a delay to ignite or after the Ignite fire fighting again! Wear appropriate protective equipment!

<u>ר</u>ו ווּ ∭

7. In case of submersion

After rescuing the vehicle from the water, deactivate the high-voltage system (see Chapter 3) and allow the water to drain. Wear appropriate protective equipment!

8. Towing / transportation / storage



Lithium-ion batteries can self-ignite, or re-ignite after a fire has been extinguished. Wear appropriate protective equipment!



If the vehicle has been involved in an accident or if the high-voltage battery is damaged or unstable: Deactivate the high-voltage system (see Section 3). Park the vehicle at a safe distance, at least 5 m, from buildings and other vehicles (quarantine area).





Do not tow a vehicle that has been involved in an accident on its drive axles.

9. Important additional information



The belt tensioners can be damaged when cutting through the B-pillar!

10. Explanation of pictograms used

